MINE INSPECTION REPORT UPDATE Q4 2007

AIR QUALITY #1 MINE, HART STREET

INSPECTION DATE: 10/10/07

AREAS INSPECTED

Unit #1 and Secondary Escapeway

<u>FINDINGS</u>		<u>LAW VIOLATED</u>
1.	14 mantrip #27 no tag on fire extinguisher	30cfr 75.1101-3
2.	No tag on fire extinguisher at oil station	30cfr 75.1101-3
3.	No tag on fire extinguisher on unit 1 scoop	30cfr 75.1101-3
4.	Corner not bolted at 7 to 8 entry intersection	30cfr 75.220(a)(1)
5.	#29 bolter needs dust box strap repaired	30cfr 75.1725(a)
6.	#29 bolter missing pin for fire suppression	30cfr 75.1103-8
7.	Water spray at feeder not working	30cfr 75.1101
8.	Escapeway markers not up to date	30cfr 75.380
9.	Fire suppression not located over battery	30cfr 75.340(a)

CORRECTIVE ACTION TAKEN

Management noted all violations and corrective actions were taken.

INSPECTION DATE: 10/25/07

AREAS INSPECTED

Unit #2 and Belts

<u>FINDINGS</u>		LAW VIOLATED
1.	No gas check in #7 entry Unit #2 scoop operator	30cfr 75.362(ii)
2.	Hole in intake walls 98 & 95 x cut Unit #2	30cfr 75.333(b)
3.	67 x cut loose top needs timber on corner 5 West B belt	30cfr 75.202(a)
4.	34 to 35 x cut 4 Main West B accumulation in roller	30cfr 75.400
5.	4 Main West A & B needs cleaned	30cfr 75.400

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to remove violations. Unit was in good condition. Made safety contact with scoop operator.

INSPECTION DATE: 11/27/07

AREAS INSPECTED

Unit 3, belt 4WB

<u>FINDINGS</u>	<u>LAW VIOLATED</u>
1. Accumulations at unit tail and back board	30cfr 75.400
2. Roof bolt plan not being followed	30cfr 75.220(a)(1)
3. No gas check by roof bolter operator unit 3	30cfr 75.362(ii)
4. Hole in intake wall 162 x cut 4WB	30cfr 75.333(h)
5. 4WB belt needs trained at 160 and 154 x cut	30cfr 75.1725(a)

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to correct.

INSPECTION DATE: 12/3/07

AREAS INSPECTED

Unit 5, Belts

<u>FINDINGS</u>	<u>LAW VIOLATED</u>
1. Guard at Unit belt tail not secured	30cfr 75.1722(a)
2. Missing strap on dust box #34 roof bolter	30cfr 75.1725(a)
3. Missing strap on dust box #31 roof bolter	30cfr 75.1725(a)

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to correct.

AIR QUALITY #1 MINE, WHEATLAND SURFACE

INSPECTION DATE: 11/7/07

AREAS INSPECTED

Surface, shops, prep-plant, & loadout

<u>FINDINGS</u>		<u>LAW VIOLATED</u>
1.	Spiral feed pump needs guard secured	30cfr 75.1722(a)
2.	Motor for fresh water pump guard needs added	30cfr 75.1722(a)

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to remove violations.

AIR QUALITY #1 WASH PLANT

INSPECTION DATE: 11/14/07

AREAS INSPECTED

Surface and prep plant

<u>FINDINGS</u>	LAW VIOLATED
1. Clean Coal Transfer head house loose guard on motor	30cfr 75.1722(a)
2. Accumulations under belts in plant	30cfr 75.400
3. Scraper Screen motor no fire extinguisher	30cfr 75.1101-3

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to correct. It is recommended that rails be installed along belts in plant.

FREELANVILLE MINE, TRIAD COAL COMPANY

INSPECTION DATE: 10/12/07

AREAS INSPECTED

Secondary Escapeway and belts from Unit to bottom

<u>FINDINGS</u>		<u>LAW VIOLATED</u>
1.	Need to clean 2 Main west belt at 116	30cfr 75.400
2.	Need to support top at 2 Main west belt back side	30cfr 75.202(a)
3.	Need to clean crosscut at 131 1 North West belt	30cfr 75.400
4.	Need to repair wall at 30 crosscut 1 Main northwest belt	30cfr 75.333(b)

CORRECTIVE ACTION TAKEN

Corrective action was taken to correct violations.

INSPECTION DATE: 10/24/07

AREAS INSPECTED

Primary escapeway

<u>FINDINGS</u> <u>LAW VIOLATED</u>

Loose roof bolt at 74 to 75 x cut Main West #2
 Need to guard hi line at door #10 x cut in Primary
 30cfr 75.202(a)
 30cfr 75.807

CORRECTIVE ACTION TAKEN

Action was taken to correct violations.

INSPECTION DATE: 12/5/07

AREAS INSPECTED

Seals and return air

FINDINGS LAW VIOLATED

1. 1.2% ch4 found in return air at seals 1SW
 2. Hole in return wall at 61x cut North West return
 30cfr 75.323(c)
 30cfr 75.333(h)

CORRECTIVE ACTION TAKEN

- 1. Adjusted air at seals to correct gas readings in return
- 2. Management noted and will correct hole in wall at 61 x cut.

FREELANDVILLE WASH PLANT #1 AND #2

INSPECTION DATE: 11/16/07

AREAS INSPECTED

Wash Plant 1 & 2

FINDINGS LAW VIOLATED

1.	Coal fines around motor ROM Belt	30cfr 75.400
2.	Coal & coal fines under tail of collection belt	30cfr 75.400
3.	Need guard on 3 rd floor of #1 plant south east side	30cfr 75.1722
4.	Electrical conduit needs repaired 3 rd floor #1 plant south east side	30cfr 75.512
5.	Need guard at 2 nd floor of #1 plant south east side	30cfr 75.1722

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to correct

FRANCISCO MINE, BLACK BEAUTY COAL COMPANY

INSPECTION DATE: 10/1/07

AREAS INSPECTED

Unit #1, Primary and Secondary Escapeways

FINDINGS LAW VIOLATED

1.	Loose top at 16+30 south west sub main crosscut in intake	30cfr 75.202 (a)
2.	Hole in intake wall at 1 st east 26 crosscut south west sub main	30cfr 75.333 (b)
3.	Need to guard hi line at 19 crosscut main south intake	30cfr 75.807

CORRECTIVE ACTION TAKEN

All violations were addressed by management.

INSPECTION DATE: 10/23/07

AREAS INSPECTED

Belts

<u>FINDINGS</u>		LAW VIOLATED
1. 9	x cut hole in wall South East Main belt intake side	30cfr 75.333(b)
2. 13	3 x cut loose rib intake side South West Main belt	30cfr 75.202(a)
3. 7	x cut hole in wall intake side South East Sub Main	30cfr 75.333(b)
4. 2	4 x cut hole in wall intake side South East Sub Main	30cfr 75.333(b)
5. 29	9 x cut hole in wall intake side South East Sub Main	30cfr 75.333(b)

CORRECTIVE ACTION TAKEN

All violations were addressed by management.

INSPECTION DATE: 11/28/07

AREAS INSPECTED

Primary escapeway

<u>FINDINGS</u> <u>LAW VIOLATED</u>

1. Need to guard hi line at more than one location in primary 30cfr 75.807

CORRECTIVE ACTION TAKEN

Management noted violation and will guard as needed.

GIBSON MINE, GIBSON COAL COMPANY

INSPECTION DATE: 10/11/07

AREAS INSPECTED

Unit #1 & #2, Secondary Escapeway

FINDINGS 1. Accumulations along rib line on Unit #1 and #2 2. Walkway on Unit 1 belt needs cleaned from 197 to 203 LAW VIOLATED 30cfr 75.400-2 30cfr 75.1403-5(g)

CORRECTIVE ACTION TAKEN

Cleaning on the unit was being done before the inspection was finished, and all other violations were addressed by management.

INSPECTION DATE: 10/26/07

AREAS INSPECTED

Unit #4, Primary to bottom

<u>FINDINGS</u>	LAW VIOLATED
1. 11x cut on Unit #4 needed cleaned	30cfr 75.400
2. Hole in wall North 42 37x cut intake side	30cfr 75.333(b)
3. 2 x cut to 7 North 42 hi voltage down	30cfr 75.807
4. 117 x cut hole in intake wall Main West	30cfr 75.333(b)
5 21 x cut hole in intake wall Main West	30cfr 75 333(b)

CORRECTIVE ACTION TAKEN

Management noted all violations and action was taken to correct.

INSPECTION DATE: 11/15/07

AREAS INSPECTED

Unit #3, Belts, 1N42, 2N42, 3A

<u>FINDINGS</u>		<u>LAW VIOLATED</u>
1.	#2x cut at 1 North 42 belt bottom roller running in coal	30cfr 75.400
2.	4 to 5x cut 1 North 42 belt bottom roller running in coal	30cfr 75.400
3.	8 to 9x cut 1 North 42 belt bottom roller running in coal	30cfr 75.400
4.	Need to clean and dust from 31 to 2x cut 1 North 42 belt	30cfr 75.400
5.	Jumper box for CO line needs repaired at 54x cut 1 North 42 belt	30cfr 75.512
6.	95x cut 2 North 2 belt bad top roller	30cfr 75.1725

CORRECTIVE ACTION TAKEN

- 1. Rollers on the 1 North 42 belt were cleaned
- 2. CO line was repaired
- 3. Bad roller at 95x cut replaced
- 4. All violations were address and corrected

INSPECTION DATE: 12/4/07

AREAS INSPECTED

Primary escapeway, Unit 1 belt

<u>FINDINGS</u>		LAW VIOLATED
1.	Tail of 3 rd 48 belt needs cleaned	30cfr 75.400
2.	Hole in intake wall 193x cut 4 th 48 belt	30cfr 75.333(h)
3.	Hole in intake wall 199x cut 4 th 48 belt	30cfr 75.333(h)
4.	Need to rock dust from head to 193x cut 4 th 48 belt float dust	30cfr 75.400

CORRECTIVE ACTION TAKEN

Management noted violation and will guard as needed.

PROSPERITY MINE, FIVE STAR COAL COMPANY

INSPECTION DATE: 10/3/07

AREAS INSPECTED

Unit #5, Secondary Escapeway, belts 3N1, 2S2, 2S1, and Main east.

<u>FINDINGS</u>	<u>LAW VIOLATED</u>
Fire extinguisher tag missing at oil station	30cfr 75.1101-3
2. 9 right on Unit #5 needed to be cleaned	30cfr 75.400-2
3. Needed flagging in faces #7, 4, 3, 3left, on Unit #5	30cfr 75.363(a)
4. 3 North head spray not working	30cfr 75.370(a)(1)
5. Need to clean belt from tail 2 South 2 to outby 28 crosscut	30cfr 75.400
6. 7 crosscut 2 South 2 fire extinguisher tag needs update	30cfr 75.1101-3
7. Head of 2 South 2 fire extinguisher tag needs update	30cfr 75.1101-3
8. Need to clean under rollers 2 South 1 tail to take-up	30cfr 75.400
9. Need tag on fire extinguisher at 6 crosscut Main east belt	30cfr 75.1101-3
10. Guard at drive motor at Main east belt needs secured	30cfr 75.1722(b)

CORRECTIVE ACTION TAKEN

Flags were hung at the faces, head spray was turned on, and all violations were noted by management and being corrected.

INSPECTION DATE: 10/22/07

AREAS INSPECTED

Surface prep plant

<u>FINDINGS</u>	<u>LAW VIOLATED</u>
1. Walkway at stacker belt needs cleaned	30cfr 75.1403-5(g)
2. U/G shop breaker box needs relabeled	30cfr 75.809
3. Fire extinguisher tag magnetite bin feeder needed update	30cfr 75.1101-3
4. Miller welder in MCC room prep plant needs leads protected	30cfr 75.517
5. L120 Volvo front light not working	30cfr 75.1725(a)
6. Fire extinguisher at fuel station out of date	30cfr 75.1101-3
7. Walk way at head of over land belt needs cleaned	30cfr 75.1403-5(g)
8. Stacker belt top roller frozen	30cfr 75.400
9. Head end of by pass belt needs fire extinguisher	30cfr 75.1100-2

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to correct.

INSPECTION DATE: 11/8/07

AREAS INSPECTED

Unit #1, Belts, 2W3, 2W2, 2W1, & 1N2

<u>FINDINGS</u>		LAW VIOLATED
1.	Single boom bolter cable run over	30cfr 75.606
2.	No fire extinguisher at oil station on unit	30cfr 75.1101-3
3.	#9 Double boom bolter cable run over	30cfr 75.606
4.	Diesel scoop bad fire extinguisher	30cfr 75.1101-3
5.	Accumulations 2 West 3 tail	30cfr 75.400
6.	Guard off at tail 2 West 3 tail	30cfr 75.1722
7.	Fire suppression not located over battery and battery charger	30cfr 75.340

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to remove violations.

INSPECTION DATE: 11/20/07

AREAS INSPECTED

Unit #2, Belts, 2N5, 2N4, 2N3, 2N2, & 2N1

<u>FINDINGS</u>		LAW VIOLATED
1.	Guard not secured at tail of unit belt	30cfr 75.1722
2.	No flag at 8R blow thru Unit 2	30cfr 75.363(a)
3.	Curtain back 64 feet from face in 6 entry Unit 2	30cfr 75.370
4.	Low air in 6 entry Unit 2	30cfr 75.208
5.	2N5 3x cut hole in intake wall	30cfr 75.333(b)
6.	Fire extinguisher at 5x cut 2N3 belt no tag	30cfr 75.1101-3
7.	Need to clean return side of 2N1 from 20 to 5x cut	30cfr 75.400

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to remove violations.

INSPECTION DATE: 11/29/07

AREAS INSPECTED

Unit #3, Belt 1s4, 1s3, 1s2, & 1s1

<u>FINDINGS</u> <u>LAW VIOLATED</u>

1.	No tag on fire extinguisher on #2 Getman motor	30cfr 75.1101-3
2.	Low air in face 4 Unit 3	30cfr 75.370
3.	Strap missing on dust box #5 roof bolter	30cfr 75.1725(a)
4.	Panic bar needed repaired operator's side #5 bolter	30cfr 75.1725(a)
5.	Clean tail of belt 1 South 1	30cfr 75.400
6.	Hole in return wall 24 x cut 1 South 1 needed sealed	30cfr 75.333(h)

CORRECTIVE ACTION TAKEN

All violations were noted and action taken to remove violations.

CARLISLE MINE, SUNRISE COAL COMPANY

INSPECTION DATE: 10/2/07

AREAS INSPECTED

Unit #1 and #2, Secondary Escapeway, and Unit belt

<u>FINDINGS</u>	LAW VIOLATED
1. 43+20 crosscut 55 hole in intake wall	30cfr 75.333(b)
2. 133 Hauler battery lid needs repaired Unit #2	30cfr 75.1725(a)
3. Feeder needs accumulations removed Unit #2	30cfr 75.400
4. Need 1 row bolts at face #3 entry Unit #2	30cfr 75.220(a)(1)
5. 50+40 crosscut 64 hole in return wall Unit #2	30cfr 75.333(b)
6. #7 entry Unit #1 needs cleaned.	30cfr 75.400
7. Roof on corners need additional support Unit #1	30cfr 75.220(a)(1)
8. Need to clean secondary markers	30cfr 75.380(d)(2)

CORRECTIVE ACTION TAKEN

All violations were noted by management and action was taken to correct.

INSPECTION DATE: 10/31/07

AREAS INSPECTED

Surface, prep plant

LAW VIOLATED FINDINGS

1. None

CORRECTIVE ACTION TAKEN

Surface was in very good condition.

INSPECTION DATE: 11/19/07

AREAS INSPECTED

Unit #1, Primary escapeway, M1 & M2 belt

FINDINGS LAW VIOLATED

1. Small hole in intake wall at 4+20 entry 6 M2 30cfr 75.333(b) 30cfr 75.370

2. Curtain back 50 feet in entry 5 Unit #1 .7% Ch 4 at miner

CORRECTIVE ACTION TAKEN

All violations were address and corrected

INSPECTION DATE: 11/30/07

AREAS INSPECTED

Primary to Unit #2

FINDINGS

1. Small hole in wall in intake (corrected by management)

LAW VIOLATED

30cfr 75.333(h)

CORRECTIVE ACTION TAKEN

All violations were address and corrected.

HAZLETON MINE, WHITE RIVER COAL

INSPECTION DATE: 10/29/07

AREAS INSPECTED

Surface prep plant

<u>FINDINGS</u> <u>LAW VIOLATED</u>

All fire extinguishers out of date
 O2 bottle not secured at mine opening
 30cfr 75.1101-3
 30cfr 75.1106-3(2)

CORRECTIVE ACTION TAKEN

All violations were noted by management.

INSPECTION DATE: 11/21/07

AREAS INSPECTED

Surface

FINDINGS LAW VIOLATED

1. Mine is closing as December and will be down to limited employees by 12/1/07

2. December 21 is closing date